


4/4



INPUT QUADRANT(S)	ROTATION OPERATION	OUTPUT QUADRANT(S)
0	-64	3
1	-64	0
0 AND 1	-64	0 AND 3
2	+64	3
1 AND 2	+128	0 AND 3
3	+64	0
2 AND 3	+64	0 AND 3
0 AND 3	NONE	0 AND 3

FIG. 12